

TCT


Certificate of Compliance

Certificate No. : TCT240815S901C
Applicant : BRAYTRON S.R.L
Address : B.DUL IULIU MANIU, NR.616, CORP B, ETAJ 1 SECTOR 6, 061129, BUCHAREST, ROMANIA
Manufacturer : DEMGRUP INTERNATIONAL LIGHTING LIMITED
Address : UNIT D 16/F, ONE CAPITAL PLACE, 18 LUARD ROAD, WAN CHAI, HONG KONG
Product : DESK LAMP
Model No. : BK06-00080 (Additional Model No. See Annex)
Trade mark : BRAYTRON

The above products have been tested by us with listed standards and found in compliance with the council LVD(Low Voltage Directive)2014/35/EU. It is possible to use CE marking to demonstrate the compliance with this Low Voltage Directive.

Test standards:	Report(s) Number	Issued By	Issued Date
EN IEC 60598-1:2021+A11:2022 EN 60598-2-4:2018 EN IEC 62031:2020+A11:2021 EN 62493:2015+A1:2022	TCT240815S901	TCT	Aug. 20, 2024

The statement is based on a single evaluation of one sample of above mentioned products. It does not imply an assessment of the whole production and does not permit the use of the test lab logo.



Tomsin

Tomsin/Senior Engineer

Aug. 20, 2024



Shenzhen TCT Testing Technology Co.,Ltd.

Hotline: 400-6611-140 Tel: 86-755-27673339 Fax: 86-755-27673332 Http://www.tct-lab.com



TCT

Annex
Certificate No.: TCT240815S901C
Additional Model No.

BK01-001XX, BK01-050XX, BK02-001XX, BK05-0001X, BK05-0050X, BK06-0001X, BK06-0050X, BK07-0001X, BK07-0050X,
BK01-002XX, BK01-051XX, BK02-002XX, BK05-0002X, BK05-0051X, BK06-0002X, BK06-0051X, BK07-0002X, BK07-0051X,
BK01-003XX, BK01-052XX, BK02-003XX, BK05-0003X, BK05-0052X, BK06-0003X, BK06-0052X, BK07-0003X, BK07-0052X,
BK01-004XX, BK01-053XX, BK02-004XX, BK05-0004X, BK05-0053X, BK06-0004X, BK06-0053X, BK07-0004X, BK07-0053X,
BK01-005XX, BK01-054XX, BK02-005XX, BK05-0005X, BK05-0054X, BK06-0005X, BK06-0054X, BK07-0005X, BK07-0054X,
BK01-006XX, BK01-055XX, BK02-006XX, BK05-0006X, BK05-0055X, BK06-0006X, BK06-0055X, BK07-0006X, BK07-0055X,
BK01-007XX, BK01-056XX, BK02-007XX, BK05-0007X, BK05-0056X, BK06-0007X, BK06-0056X, BK07-0007X, BK07-0056X,
BK01-008XX, BK01-057XX, BK02-008XX, BK05-0008X, BK05-0057X, BK06-0008X, BK06-0057X, BK07-0008X, BK07-0057X,
BK01-009XX, BK01-058XX, BK02-009XX, BK05-0009X, BK05-0058X, BK06-0009X, BK06-0058X, BK07-0009X, BK07-0058X,
BK01-010XX, BK01-059XX, BK02-010XX, BK05-0010X, BK05-0059X, BK06-0010X, BK06-0059X, BK07-0010X, BK07-0059X,
BK01-011XX, BK01-060XX, BK02-011XX, BK05-0011X, BK05-0060X, BK06-0011X, BK06-0060X, BK07-0011X, BK07-0060X,
BK01-012XX, BK01-061XX, BK02-012XX, BK05-0012X, BK05-0061X, BK06-0012X, BK06-0061X, BK07-0012X, BK07-0061X,
BK01-013XX, BK01-062XX, BK02-013XX, BK05-0013X, BK05-0062X, BK06-0013X, BK06-0062X, BK07-0013X, BK07-0062X,
BK01-014XX, BK01-063XX, BK02-014XX, BK05-0014X, BK05-0063X, BK06-0014X, BK06-0063X, BK07-0014X, BK07-0063X,
BK01-015XX, BK01-064XX, BK02-015XX, BK05-0015X, BK05-0064X, BK06-0015X, BK06-0064X, BK07-0015X, BK07-0064X,
BK01-016XX, BK01-065XX, BK02-016XX, BK05-0016X, BK05-0065X, BK06-0016X, BK06-0065X, BK07-0016X, BK07-0065X,
BK01-017XX, BK01-066XX, BK02-017XX, BK05-0017X, BK05-0066X, BK06-0017X, BK06-0066X, BK07-0017X, BK07-0066X,
BK01-018XX, BK01-067XX, BK02-018XX, BK05-0018X, BK05-0067X, BK06-0018X, BK06-0067X, BK07-0018X, BK07-0067X,
BK01-019XX, BK01-068XX, BK02-019XX, BK05-0019X, BK05-0068X, BK06-0019X, BK06-0068X, BK07-0019X, BK07-0068X,
BK01-020XX, BK01-069XX, BK02-020XX, BK05-0020X, BK05-0069X, BK06-0020X, BK06-0069X, BK07-0020X, BK07-0069X,
BK01-021XX, BK01-070XX, BK02-021XX, BK05-0021X, BK05-0070X, BK06-0021X, BK06-0070X, BK07-0021X, BK07-0070X,
BK01-022XX, BK01-071XX, BK02-022XX, BK05-0022X, BK05-0071X, BK06-0022X, BK06-0071X, BK07-0022X, BK07-0071X,
BK01-023XX, BK01-072XX, BK02-023XX, BK05-0023X, BK05-0072X, BK06-0023X, BK06-0072X, BK07-0023X, BK07-0072X,
BK01-024XX, BK01-073XX, BK02-024XX, BK05-0024X, BK05-0073X, BK06-0024X, BK06-0073X, BK07-0024X, BK07-0073X,
BK01-025XX, BK01-074XX, BK02-025XX, BK05-0025X, BK05-0074X, BK06-0025X, BK06-0074X, BK07-0025X, BK07-0074X,
BK01-026XX, BK01-075XX, BK02-026XX, BK05-0026X, BK05-0075X, BK06-0026X, BK06-0075X, BK07-0026X, BK07-0075X,
BK01-027XX, BK01-076XX, BK02-027XX, BK05-0027X, BK05-0076X, BK06-0027X, BK06-0076X, BK07-0027X, BK07-0076X,
BK01-028XX, BK01-077XX, BK02-028XX, BK05-0028X, BK05-0077X, BK06-0028X, BK06-0077X, BK07-0028X, BK07-0077X,
BK01-029XX, BK01-078XX, BK02-029XX, BK05-0029X, BK05-0078X, BK06-0029X, BK06-0078X, BK07-0029X, BK07-0078X,
BK01-030XX, BK01-079XX, BK02-030XX, BK05-0030X, BK05-0079X, BK06-0030X, BK06-0079X, BK07-0030X, BK07-0079X,
BK01-031XX, BK01-080XX, BK02-031XX, BK05-0031X, BK05-0080X, BK06-0031X, BK06-0080X, BK07-0031X, BK07-0080X,
BK01-032XX, BK01-081XX, BK02-032XX, BK05-0032X, BK05-0081X, BK06-0032X, BK06-0081X, BK07-0032X, BK07-0081X,
BK01-033XX, BK01-082XX, BK02-033XX, BK05-0033X, BK05-0082X, BK06-0033X, BK06-0082X, BK07-0033X, BK07-0082X,
BK01-034XX, BK01-083XX, BK02-034XX, BK05-0034X, BK05-0083X, BK06-0034X, BK06-0083X, BK07-0034X, BK07-0083X,
BK01-035XX, BK01-084XX, BK02-035XX, BK05-0035X, BK05-0084X, BK06-0035X, BK06-0084X, BK07-0035X, BK07-0084X,
BK01-036XX, BK01-085XX, BK02-036XX, BK05-0036X, BK05-0085X, BK06-0036X, BK06-0085X, BK07-0036X, BK07-0085X,

Shenzhen TCT Testing Technology Co.,Ltd.

Hotline: 400-6611-140 Tel: 86-755-27673339 Fax: 86-755-27673332 [Http://www.tct-lab.com](http://www.tct-lab.com)



TCT

BK01-037XX, BK01-086XX, BK02-037XX, BK05-0037X, BK05-0086X, BK06-0037X, BK06-0086X, BK07-0037X, BK07-0086X,
BK01-038XX, BK01-087XX, BK02-038XX, BK05-0038X, BK05-0087X, BK06-0038X, BK06-0087X, BK07-0038X, BK07-0087X,
BK01-039XX, BK01-088XX, BK02-039XX, BK05-0039X, BK05-0088X, BK06-0039X, BK06-0088X, BK07-0039X, BK07-0088X,
BK01-040XX, BK01-089XX, BK02-040XX, BK05-0040X, BK05-0089X, BK06-0040X, BK06-0089X, BK07-0040X, BK07-0089X,
BK01-041XX, BK01-090XX, BK02-041XX, BK05-0041X, BK05-0090X, BK06-0041X, BK06-0090X, BK07-0041X, BK07-0090X,
BK01-042XX, BK01-091XX, BK02-042XX, BK05-0042X, BK05-0091X, BK06-0042X, BK06-0091X, BK07-0042X, BK07-0091X,
BK01-043XX, BK01-092XX, BK02-043XX, BK05-0043X, BK05-0092X, BK06-0043X, BK06-0092X, BK07-0043X, BK07-0092X,
BK01-044XX, BK01-093XX, BK02-044XX, BK05-0044X, BK05-0093X, BK06-0044X, BK06-0093X, BK07-0044X, BK07-0093X,
BK01-045XX, BK01-094XX, BK02-045XX, BK05-0045X, BK05-0094X, BK06-0045X, BK06-0094X, BK07-0045X, BK07-0094X,
BK01-046XX, BK01-095XX, BK02-046XX, BK05-0046X, BK05-0095X, BK06-0046X, BK06-0095X, BK07-0046X, BK07-0095X,
BK01-047XX, BK01-096XX, BK02-047XX, BK05-0047X, BK05-0096X, BK06-0047X, BK06-0096X, BK07-0047X, BK07-0096X,
BK01-048XX, BK01-097XX, BK02-048XX, BK05-0048X, BK05-0097X, BK06-0048X, BK06-0097X, BK07-0048X, BK07-0097X,
BK01-049XX, BK01-098XX, BK02-049XX, BK05-0049X, BK05-0098X, BK06-0049X, BK06-0098X, BK07-0049X, BK07-0098X,
(X=0, 1, 2, 3, 4, 5, 6, 7, 8, 9)

TCT

Shenzhen TCT Testing Technology Co.,Ltd.

Hotline: 400-6611-140 Tel: 86-755-27673339 Fax: 86-755-27673332 [Http://www.tct-lab.com](http://www.tct-lab.com)

